



# NÁVOD NA MONTÁŽ CT-767




1



2

















3



4



|  |  |  |  |
|--|--|--|--|
| <b>A x 1</b>  | <b>E x 1</b>                | <b>I x 8</b>                | <b>M x 1</b>  |
| <b>B x 1</b>  | <b>F x 1</b>                | <b>J x 8</b>                | <b>N x 1</b>  |
| <b>C x 1</b>  | <b>G x 4</b>                | <b>K x 4</b> <br>M6 x 13 mm |  |
| <b>C x 1</b>  | <b>H x 8</b> <br>M6 x 35 mm | <b>L x 4</b>                |  |

